

North Carolina Highway Safety Improvement Program

Potentially Hazardous Intersection Locations in HENDERSON County

2011 Cycle

PH Number					Overall
State Rank	Total Weight	Divison SHP Troop	Region	Location	Crashes Severity Index
44I00108					26
263	1.71	14 G	BLUE RIDGE	HENDERSON (HENDERSONVILLE) SR 1722 (MP 1.14) AT SR 1775 (MP 0.85)	7.05
Excluded: <input checked="" type="checkbox"/> Comments: Analyzed during 2010 HSIP Cycle					
44I00106					72
617	1.12	14 G	BLUE RIDGE	HENDERSON (RURAL) US 64 (MP 10.61) AT US 25B (MP 5.66)	3.26
Excluded: <input type="checkbox"/> Comments:					
44I00103					75
683	1.04	14 G	BLUE RIDGE	HENDERSON (HENDERSONVILLE) US 64 WB COUPLET (MP 10.65) AT US 25B (MP 5.72)	3.79
Excluded: <input type="checkbox"/> Comments:					
44I00126					73
737	0.99	14 G	BLUE RIDGE	HENDERSON (HENDERSONVILLE) US 64 WB COUPLET (MP 10.51) AT US 25B SB COUPLET (MP 5.58)	3.33
Excluded: <input type="checkbox"/> Comments:					
44I00107					60
925	0.85	14 G	BLUE RIDGE	HENDERSON (RURAL) US 25B (MP 2.73) AT SR 1783 (MP 1.08)	3.84
Excluded: <input type="checkbox"/> Comments:					
44I00086					21
1242	0.64	14 G	BLUE RIDGE	HENDERSON (RURAL) SR 1331 (MP 0.60) AT SR 1426 (MP 0.95)	6.72
Excluded: <input type="checkbox"/> Comments:					
44I00091					41
1329	0.59	14 G	BLUE RIDGE	HENDERSON (HENDERSONVILLE) US 64 (MP 10.36) AT US 64 WB COUPLET (MP 10.36)	3.71
Excluded: <input type="checkbox"/> Comments:					
UNK					35
1362	0.57	14 G	BLUE RIDGE	HENDERSON (RURAL) SR 1722 (MP 0.93) AT SR 1779 (MP 0.87)	5.49
Excluded: <input type="checkbox"/> Comments:					
44I00129					60
1496	0.5	14 G	BLUE RIDGE	HENDERSON (RURAL) US 64 (MP 10.47) AT US 25B SB COUPLET (MP 5.51)	2.36
Excluded: <input type="checkbox"/> Comments:					

North Carolina Highway Safety Improvement Program

Potentially Hazardous Intersection Locations in HENDERSON County

2011 Cycle

PH Number					Overall					
State Rank	Total Weight	Divison SHP Troop	Region	Location	Crashes Severity Index					
44I00124					28	WARRANT INFORMATION				
1743	0.38	14 G	BLUE RIDGE	HENDERSON (HENDERSONVILLE) US 25B (MP 4.53) AT CHADWICK	3.38	Warrant	Crashes	Percent	Severity	Weight
Excluded: <input type="checkbox"/> Comments:						I-1	15	53.6%	3.96	0.38
44I00130					28	WARRANT INFORMATION				
1782	0.36	14 G	BLUE RIDGE	HENDERSON (HENDERSONVILLE) US 64 (MP 10.68) AT GROVE	2.85	Warrant	Crashes	Percent	Severity	Weight
Excluded: <input type="checkbox"/> Comments:						I-1	19	67.9%	2.95	0.36
UNK					26	WARRANT INFORMATION				
1842	0.32	14 G	BLUE RIDGE	HENDERSON (RURAL) SR 1171 (MP 8.77) AT SR 1173 (MP 0.22)	2.99	Warrant	Crashes	Percent	Severity	Weight
Excluded: <input type="checkbox"/> Comments:						I-5	26	CROSSING	2.76	0.32
44I00131					42	WARRANT INFORMATION				
1854	0.31	14 G	BLUE RIDGE	HENDERSON (HENDERSONVILLE) US 25B SB COUPLET (MP 5.02) AT SR 1127 (MP 11.21)	2.41	Warrant	Crashes	Percent	Severity	Weight
Excluded: <input type="checkbox"/> Comments:						I-1	27	64.3%	1.82	0.31
44I00110					29	WARRANT INFORMATION				
1909	0.27	14 G	BLUE RIDGE	HENDERSON (RURAL) SR 1006 (MP 8.39) AT SR 1734 (MP 0.88)	2.79	Warrant	Crashes	Percent	Severity	Weight
Excluded: <input type="checkbox"/> Comments:						I-1	21	72.4%	2.06	0.27
44I00116					33	WARRANT INFORMATION				
1956	0.21	14 G	BLUE RIDGE	HENDERSON (HENDERSONVILLE) US 25B (MP 5.46) AT THIRD (MP 1.18)	2.12	Warrant	Crashes	Percent	Severity	Weight
Excluded: <input type="checkbox"/> Comments:						I-1	18	54.5%	1.82	0.21
44I00098					27	WARRANT INFORMATION				
1956	0.21	14 G	BLUE RIDGE	HENDERSON (HENDERSONVILLE) US 64 WB COUPLET (MP 10.58) AT MAIN (MP 0.72)	2.64	Warrant	Crashes	Percent	Severity	Weight
Excluded: <input type="checkbox"/> Comments:						I-1	18	66.7%	1.82	0.21